

NORTH CAROLINA

Department of Transportation



















C203929 (I-5765)

Marcus Kiser / David Carr

2018 NCDOT / AGC Workshop


Project Overview

• Project Length: 6.357 miles

 <u>Location</u>: I-40 (Davie County) from Mile Marker 169.14 to Mile Marker 175.39

 Scope of Work: Concrete Patching, Full Depth Shoulder Repair, Latex Overlay, Complete Asphalt Overlay

Divided into 3 Segments



Project Challenges

High volume and high speed traffic on I-40

- Long straight tangent sections of highway
- Area known for hydroplaning

 ICT For Farmington Road (New Davie County High School Grand Opening)

Project Challenges Continued




ncdot.gov



ncdot.gov





ncdot.gov



Traffic Control Aids

Smart Work Zone

Extra Message Boards at department's expense

Overhead Message board coordination with TMC

Law Enforcement (HAWKS)

Segment 1

- Work began on 3-19-17 (two weeks early)
- Work began with full depth shoulder milling/repair, shoulder drain installation and removal and reinstallation of guardrail.
- Plans called for 4ft. Median and 10ft. Right Shoulder
- We installed 7ft. Median and 7ft. Right Shoulder.
- This allowed for more working room with upcoming traffic shifts.


Full Depth Shoulder




Segment 1 Continued

- ICT 3 required Farmington Road Interchange open prior to 8-14-17. If the ICT was met, the contractor would receive an incentive (ie. Bonus)
- Segment 1 crossovers CD & EF began on 3-27-17
- While crossovers CD & EF were being built, crews continued to perform work simultaneously on full depth shoulder repair, shoulder drain installation and remove & reset guardrail (ie. Multitasking) in the WB lanes utilizing single lane closures.
- This gave us a head start on the required work in the WB direction.

Crossovers CD & EF





Segment 1 Continued

 Crossover CD & EF with concrete barrier wall installation was completed and WB traffic was switched to the EB lanes on 4-20-17. (Approximately 4 weeks after construction began.)

Crossover / Concrete Barrier Wall



Segment 1 Continued

- Crews were nearing completion of the required work in segment 1 WB lanes on 6-4-17, so traffic was taken out of the head to head pattern by removing the barrier wall.
- Crews utilized single lane closures to finish up the remaining work in the WB direction by 6-9-17.
- From 6-4-17 6-9-17, crews were reconfiguring the concrete barrier wall in the crossover to allow for traffic to be switched from EB to WB lanes.

Segment 1 continued

- On 6-9-17, segment 1 WB direction work was complete along with the reconfiguration of the concrete barrier wall.
 This allowed crews to switch EB traffic to the WB lanes in a head to head pattern.
- With traffic switched to a head to head pattern, crews shut down EB on / off ramps to Farmington Road which allowed them to begin construction operations in the EB lanes of segment 1.

Segment 1 complete

 Crews actively pursued the work in segment 1 in order to meet the 8-14-17 ICT.

Crews completed ICT 3 on 8-7-17 (1 week early)

Segment 2

- Preliminary discussions with the engineering staff considered eliminating crossover AB which would have required segment 2 to be constructed under single lane closures.
- Project Inspector and Project Superintendent highly advised that crossover AB be constructed so segments 2 could be built using the same method as segment 1.


Segment 2 Continued


 Required work: Full Depth Shoulder Repair, Extensive Concrete Patching, Hydro Demo / Latex Overlay on Bridge # 61, 62, & 74, 75 Segment 2 Continued





Segment 2 Continued





Remaining Work

- Segment 2 is substantially complete using the same method and procedures as segment 1
- Remaining work to be completed is essentially segment 3 and an 1.5" overlay throughout the entire project.
- Percent complete to date: 80%
- Percent Complete by progress chart: 47%
- Project is 33% ahead of schedule

Communication

- TMC
- STOC
- Maintenance
- IMAP
- Pavement Management
- Work Zone Safet
- Area Engineers

- SHP and Hawks
- Surrounding Businesses
- Media
- Contractor

Contractor Comments

- Work zone safety is our number one priority
- Assisted in clearing accidents from the work zone
- Understood schedule urgency
- Requested "pre" preconstruction meeting to discuss concerns and ideas prior to award
- Subcontractor coordination very critical
- Work continues